

**CORNWALL HISTORIC CHURCHES TRUST
GRANTS MADE MARCH 2007 TO SEPTEMBER 2024**

The 325 Grants, totalling £1,089,345 were made with Cornwall Historic Churches Trust funds, funds provided to the Cornwall Historic Churches Trust by The Duke of Cornwall's Benevolent Fund, The Cornwall Heritage Trust and Partnership Grants made by the National Churches Trust on the recommendation of the Cornwall Historic Churches Trust.

325	19 September 2024	St Sampson South Hill	Repointing and repairs to tower	£6,000
324	19 September 2024	Madron	Replacment of ringing chamber celing	£4,100
323	19 September 2024	St Mellion, St Merlanus	Repairs to joists and timbers in tower clock room	£5,000
322	19 September 2024	Crowan	Repairs to tower doors, repointing, chimney capping and making good gable ends	£3,000
321	19 September 2024	Portscatho United Church	Replacement of roof & insulation work	£5,000
320	19 September 2024	High Street Methodist, Penzance	Urgent remedial electrical work	£700
319	09 July 2024	St Mawgan in Pydar	Kickstart Grant	£500
318	12 July 2024	St Dominick	Maintenance Grant	£500
317	19 June 2024	Pelynt	Maintenance Grant	£500
316	16 May 2024	Kenwyn	Replacement of rainwater goods	£5,000
315	16 May 2024	Mawla Methodist Chapel	Window Repairs	£1,000
314	16 May 2024	St Sampson South Hill	Overhaul and replacement of rainwater goods	£5,000
313	16 May 2024	Come to Good Meeting House	Renewal of thatch roof, upgrading of heating and repairs to associated bulding	£13,900
312	16 May 2024	St Mawgan in Pydar	Repairs to bells and metalwork of frame	£1,300
311	03 May 2024	Menheniot	Maintenance Grant	£500
310	16 April 2024	Lewannick	Maintenance Grant	£500
309	28 March 2024	Portscatho URC	Kickstart Grant	£500
308	29 February 2024	Madron	Kickstart Grant	£500
307	14 February 2024	St John's Bodinnick	Maintenance Grant	£500
306	21 March 2024	Camborne Methodist Church	Major repairs to windows	£10,000
305	21 March 2024	St Ewe	Repairs to leaking roof	£1,000
304	14 February 2024	St Ewe	Maintenance Grant	£500
303	13 February 2024	St Winwaloe Church, Tremaine	Maintenance Grant	£500
302	18 January 2024	Probus, St Probus and St Grace	Repointing of SW gable and drainage work	£1,800
301	18 January 2024	St Dennis	Restoration of bells and fittings	£3,300
300	18 January 2024	Rock Methodist Chapel	Replacement of roof	£6,000
299	18 January 2024	St Winnow Parish Church	Replace stonework around windows and re-glaze tracery	£4,600
298	23 October 2023	St Goran, Gorran	Maintenance Grant	£500
297	23 October 2023	St Just, Gorran Haven	Maintenance Grant	£500
296	15 July 2023	St Mewan	Maintenance Grant	£500
295	28 September 2023	St Briget's Morvah	Repairs to Polyphant stone windows	£8,000

294	28 September 2023	St Goran, Gorran	Repairs to SW gable and repairs to stop water ingress	£4,500
293	28 September 2023	St Denys, N Tamerton	Repairs and restoration of bells	£5,000
292	28 September 2023	Zion Community Church, St Ives	Exterior repairs to make building watertight	£1,000
291	28 September 2023	St Sampson South Hill	Pointing and repairs to external masonry around tower, chancel and Manaton chapel	£6,000
290	28 September 2023	St Julitta, Lanteglos	Repairs to medieval glass and windows	£8,000
289	28 September 2023	Pelynt	Repairs to tower roof	£1,000
288	13 June 2023	Pillaton St Odulph	Maintenance Grant	£372
287	13 June 2023	St Mellion, St Merlanus	Maintenance Grant	£336
286	13 June 2023	Maker	Repointing of tower pinnacles and parapets, renewal of tower roof	£7,000
285	12 February 2023	St Stephen in Brannel	Maintenance Grant	£500
284	20 February 2023	Par	Maintenance Grant	£500
283	17 May 2023	Antony, St James The Great	Kickstart Grant	£500
282	15 May 2023	St Blazey	Maintenance Grant	£500
281	22 March 2023	Sticker	Maintenance Grant	£500
280	24 May 2023	Egloskerry	Re-roofing of south aisle and new downpipe	£4,500
279	24 May 2023	St Mawgan in Meneage	Repointing of pinnacles, work to prevent water ingress between tower and roof	£2,500
278	09 March 2023	St Paul's Charlestown	Replacement of North Aisle roof, additional rainwater goods	£7,000
277	09 March 2023	Penzance Baptist Church	Replacement of main front doors	£1,600
276	05 January 2023	St Clarus, St Cleer	To replace and augment the existing ring of bells from 6 to 8, retuning and repairs to frames	£6,300
275	16 December 2022	Laneast	Repairs to south door jamb	£380
274	26 November 2022	St Sampson South Hill	Repairs to South Porch	£1,000
273	28 October 2022	St Mawnan, Mawnan Smith	Repairs to plasterwork	£900
272	13 October 2022	St Clarus, St Cleer	To replace and augment the existing ring of bells from 6 to 8, retuning and repairs to frames	£2,700
271	05 July 2022	Leedstown Methodist	Repairs to ceiling and plasterwork, protection and cleaning of the organ	£700
270	25 May 2022	St Grada, Grade	Re-roofing, additional award	£5,000
269	25 May 2022	Truro Cathedral	Repairs to roof of St Mary's Aisle, additional award	£6,000
268	25 May 2022	Marazion Methodist	Treatment of water ingress, repairs to leadwork and repairs to ornate plaster	£2,600
267	25 May 2022	High Street Methodist, Penzance	Repairs to ceiling following falls of lime plaster	£2,100
266	03 March 2022	St Mawgan in Meneage	Emergency repairs to heating system and tower to prevent water ingress	£500
265	03 March 2022	St Mawes	Repairs to west wall and installation of slate hanging on west façade	£5,000
264	20 January 2022	St Ia, St Ives	Repairs to clock on tower	£2,000
263	20 January 2022	Lamorran	Additional replastering work on ceilings to contain bats	£4,000
262	23 September 2021	St Andrew's Stratton	Repairs to chancel roof, protecting headstones and monuments below	£3,000
261	23 September 2021	Connect Church, Wadebridge	Replace roof, repair windows, dryline interior wall	£1,000
260	23 September 2021	Carharrack Methodist Church	Improvements to lead weatherings, replastering, repointing and joinery repairs	£1,000
259	23 September 2021	St Clether	Treatment of beetle infestation in roof timbers and essential electrical work	£1,000
258	23 September 2021	Truro Cathedral	Repairs to roof, stonework and rainwater goods of St Mary's Aisle	£4,000

257	23 September 2021	Our Lady & St Neot, Liskeard (RC)	Repairs to slate work adjacent to main road, water seepage & damp, stabilisation of stone cross	£2,000
256	23 September 2021	St Tudy Methodist	Reslate roof and repairs to windows	£2,000
255	23 September 2021	St Just in Roseland	Replacement electric cable	£1,000
254	24 June 2021	Marazion Quaker Meeting House	New roof and heating system	£4,000
253	24 June 2021	St Grada, Grade	Re-roofing, repointing and replacement of rainwater goods	£5,000
252	24 June 2021	St Sampson, South Hill	Gutter repairs and re-leading	£3,000
251	24 June 2021	All Saints, Tuckingmill	Replacement of louvres in tower	£2,500
250	04 February 2021	St Julitta, Lanteglos	Repairs to rope chamber in tower	£1,000
249	04 February 2021	Lamorran	Internal repairs to enable reopening of the church	£5,000
248	04 February 2021	St Neot	Repairs to medieval windows	£5,000
247	04 February 2021	Penzance Catholic Church	Damp proofing to lower crypt walls and floor	£2,000
246	08 October 2020	St Mary's Launceston	Repair work to clock	£2,000
245	08 October 2020	St John the Evangelist, Treslothan	Urgent roof repairs arising from QI	£1,000
244	08 October 2020	St Michael's Budehaven	Repairs to bellcote	£2,000
243	08 October 2020	St Sampson, South Hill	Window repairs	£3,000
242	08 October 2020	St Martin of Tours, Werrington	New Boiler	£1,500
241	08 October 2020	St Pol de Leon Paul	Repairs to two windows	£1,000
240	13 May 2020	St Stephens Launceston	New Roof	£5,000
239	12 March 2020	St Germans	Repairs to stop dry rot in North and South walls, renew leadwork, repointing and work to stop water ingress	£10,000
238	12 March 2020	St Probus and St Grace, Probus	Repairs to tower and reroofing of North Aisle	£5,000
237	12 March 2020	St Martin's Lewannick	Repairs to windows, replastering, replacing floors and restoration of organ	£2,000
236	12 March 2020	St Neot	Repairs to North wall to prevent ingress of water	£5,000
235	08 October 2019	Trevenson, Illogan	Rewiring, new heating and lighting	£1,400
234	08 October 2019	Cornerstone Torpoint	Rebuilding of boundary structural wall	£2,600
233	08 October 2019	St Michael Helston	Repairs to floor and replacement of tiles	£2,000
232	08 October 2019	St Mary's Biscovey	Fast Track Maintenance Grant for repairs to tower	£1,700
231	08 October 2019	Lanteglos-by-Camelford, St. Julitta.	Replacement of tower roof	£3,000
230	08 October 2019	St Mary's Merrymeet	Repairs to fleche to stabilise it while plans are drawn up for major renovation	£1,000
229	03 June 2019	Carbis Bay Methodist Church	Repairs to Tower (Fast Track Maintenance)	£900
228	03 June 2019	St Sampson, Golant	Repairs to Rainwater Goods (Fast Track Maintenance)	£1,000
227	03 June 2019	St Sithney, Sithney	Replacement of floor and associated archaeological work	£5,000
226	03 June 2019	Our Lady of the Sea & St Anthony, St Mawes	Replacement of stained glass window	£150
225	03 June 2019	Old Kea	Repairs to four pillars, supporting valley roof, replacement of stonework	£2,000
224	14 March 2019	Truro Methodist Church	Repairs to ceiling and plaster bosses	£1,000
223	14 March 2019	St Julitta, Lanteglos	Replacement of rotten medieval timbers	£5,000
222	14 March 2019	St Mary's Sheviock	Overhaul of bell fittings, repainting of metalwork and treatment of floors. Replacement of bell ropes	£5,000
221	14 March 2019	Penryn Methodist Church	Roof Repairs	£600
220	14 March 2019	St Mary the Virgin, Bradoc	Installation of LED lights	£500
219	14 March 2019	St George the Martyr, Nanpean	Repairs to ensure building is safe & watertight, especially nave ceiling and roof above. Repairs to chimney and rainwater goods.	£1,800
218	14 March 2019	Falmouth Methodist Church	Essential Fire Prevention Upgrade	£2,000
217	14 March 2019	Fowey Parish Church	Renew all slates on North Aisle and replace rotten timbers	£3,400

216	14 March 2019	Truro RC, Our Lady of the Portal and St Piran	Flat roof needs replacement	£1,400
215	14 March 2019	Antony, St James The Great	Repair & Restore two Willimott windows	£1,500
214	09 October 2018	Calstock, St Andrew's Church	Bells.	£2,500
213	09 October 2018	Landulph	<ul style="list-style-type: none"> • Replace the lead roof to the tower, and small access tower to the roof, and the perimeter lead gutter. • Repair cracks in parapet stonework and roof access tower. • Renew door to the access tower. • Remove perimeter flashings and renew • Renew the sarking boarding beneath the lead and replace any rotting timbers. • Provide a tower hoist to get materials up and down from the roof. • Provide temporary safety railing around the perimeter parapet. • Repair/replace cast iron rainwater pipe at North end of tower. 	£5,500
212	09 October 2018	Lelant, St Uny	<p>Serious problems with the floor, part of which is already unusable. So far, we have raised approximately two thirds of the £ 141,000 (plus VAT) needed for this urgent work. We have already raised money for, and repaired, the tower. The bell frame is being repaired this autumn but funds received for this would enable us to progress our money raising for the floor being repaired this autumn.</p> <p>(Also we have no disabled access nor internal toilets, and no facilities that could be uses by the wider community. The associated charities with whom you co-operate may be willing to give a grant towards our plans to install these.)</p>	£5,000
211	09 October 2018	Withiel, St Clements	Maintenance Grant	£1,000
210	25 June 2018	Zennor	<p>Due to corrosion over the last 90 years, the bell frame is in a dangerous condition and the bells can no longer be rung. The bells need some restorative work.</p> <p>Bell frame and bells to be removed from the tower.</p> <p>Bell frame to be rebuilt.</p> <p>Bell fittings to be restored and old timber fittings replaced.</p> <p>Bell wheels to be refurbished.</p> <p>Bells to be re-tuned.</p>	£7,500
209	25 June 2018	St. Michael's Perranporth	Our objective with this project is to upgrade our seriously outdated heating system. The current electric heaters are over 40 years old and are now in need or removal, replacement with a more efficient up to date heating system. The PCC has decided that an under floor system would greatly improve our carbon footprint and at the same time help us to reduce our energy costs	£1,000
208	25 June 2018	North Petherwin, St Paternus	<p>For viewing work, cut out corroded Polyphant stone, make and re-fit with N H L 3.5 and coarse sand.</p> <p>Mortar to be analysed by the Cornish Lime Company.</p> <p>To drill and fit Cin Tec sock anchors to arch 24 number, 12 each side to a depth of 850 and 1,200 mm.</p>	£500

207	25 June 2018	St Just-in-Penwith Parish Church	The roof was thought to have last been fully replaced in 1866 when the original waggon style roof was replaced with new Deal timbers and slates. We are looking to: Complete re-roofing of the church utilising Cornish slates Re-leading main valleys to ensure compliance with current guidelines and best practice. Carpentry works and repairs related to the above using traditional techniques, materials and methods Ceiling repairs using lath and lime plaster Masonry repairs to strengthen wall heads etc. Overhauling rainwater goods and low level drainage to ensure water is able to be taken effectively from the main body of the church. Removal of defective and unsafe chimney which is leaning heavily and in need of urgent attention and repair. Re-pointing works to remove defective pointing and inappropriate cement based mortars.	£13,500
206	25 June 2018	St Ewe	1. Urgent work to cure dampness in Spire by removing cement based motar and re-pointing with Lime. 2. To address structural weakness in Spire resulting from Bell Frame main supports corroding	£13,500
205	25 June 2018	Blisland, St Protus and St Hyacinth	The vestry is an add-on in the 17th century we believe. The doorway is some three feet deep. The supporting beams have rotted through due to the pointing of the outer wall and doorway having been eroded due to weather. We need to replace like with like wooden beams and re-plaster internally and re-point outside. We also need to repair the door to the vestry.	£2,000
204	23 March 2018	Zion Community Church,	1. Improving the fire safety of our facilities, in accordance with the actions of a Rand Survey conducted in 2015. 2. Improving our presence in the town through necessary maintenance. 3. Making our facilities more disabled and family friendly.	£2,100
203	23 March 2018	Lelant, St Uny	The restoration of the tower and bell chamber including lifting the lead, the renewal of roof and floor timbers, the rebuilding and strengthening of parapets and the replacement of broken downpipes. The tower will be repointed with lime mortar (all cement pointing and interior cement wash to be removed).	£2,000
202	23 March 2018	st mawes	To remove and have repaired the vestry window and the central window on the north side of the church, both of which are in a very poor state.	£2,500
201	23 March 2018	Shevioc, St Mary's	Approximately 95% of the joints in the tower and spire are loose or hollow and the tower and spire is now listed on the English Heritage At Risk register. There has been a very recent fall of timber within the tower and signs of increasing water penetration which drive an urgent need to safely remove the two bells. Works will include the installation of a safe means of access to the bells so that they and the bell paraphernalia can be inspected, repaired and maintained in the future. The plaster ceiling in the nave was identified as Priority A in the 2013 Quinquennial Report and has subsequently been netted. The Quinquennial inspection of April 2017 also recommended the need to survey and repair the roof bosses during the repairs to the plaster ceiling.	£4,000
200	23 March 2018	Perranporth Methodist Church,	Removing cement mortar strap pointing form roadside face of church building and replacing with flush lime mortar.	£1,300
199	23 March 2018	Penzance RC	Within a development of the crypt levels of the church to give us parish & community facilities to include kitchen, toilets and disabled access (separate funding mostly in place), we are also needing to carry out repairs at crypt level to lintels and stone work to support the church above. This is obviously necessary (rather than desirable) work and is rather urgent & requires completion within the same time period as the separately funded facilities development work detailed above	£6,500

198	23 March 2018	Lanhydrock, St.Hydroc	In recent years Quinquennial Inspection reports have identified problems of damage due to water ingress , arising from deterioration of roof leadwork and slate roofs , and both high and low level drainage, uch that the church structure is no longer fully weatherproof , and in need of increasingly urgent repair. A project has been prepared , which will comprise:- a) replacement of two large leadwork valleys in the roof , and associated overflows b) repair of slate roofs c) replacement of leaking cast iron guttering d) refurbishment of low level drainage e) making good water damage to the interior of the church	£7,500
197	23 March 2018	Gwennap, St. Wenappa	2015: Plaster on the internal southwest wall was stripped to allow the wall to dry out. External repointing in lime mortar- replacing old cement work - was carried out at that time. The internal wall is now dry adeady for re-plastering in lime.	£2,500
195	11 October 2017	Breage, St Breaca Church,	Tower Work. Accessing the pinnacles with scaffolding, removing defective pinning and fixings, dissembling the same, re-securing, pinning, bedding and pointing upon completion. Whilst scaffolding is erected, high level pointing will be undertaken to the	£5,000
194	11 October 2017	Camborne Wesley Methodist Church	Murray is teasing out eligible work from an application that was largely ineligable. Likely to be security doors and health and safty issues.	£4,500
193	11 October 2017	Cawsand Congregational Church	For Adjustment	£500
192	11 October 2017	Lanhydrock, St.Hydroc	a) replacement of two large leadwork valleys in the roof , and associated overflows b) repair of slate roofs c) replacement of leaking cast iron guttering d) refurbishment of low level drainage e) making good water damage to the interior of the church	£4,500
191	11 October 2017	Linkinhome, St Melor's	Restoration work on two paintings as set out in Grant Application	£300
190	11 October 2017	Portscatho United Church	Various works to Porch	£1,850
189	11 October 2017	Quethiock, St Hugh	Two windows on the North wall have suffered movement due to failure of metalwork at their base .The glass will be removed and mullions hydraulically returned to the correct position, before making good and replacing the glass. The windows are part of the	£3,000
188	11 October 2017	Veryan	Retrospective application for weather proofing the Tower following storm damage. The Clock was covered by insurance, but the "making good" was not. The actual cost exceeded the estimate.	£3,000
187	11 October 2017	Wendron, St Wendrona	Repair work to roof areas including: Renewal of north and south facing slopes Minor repairs to central slopes Repair to porch roof Repair to tower roof also joinery and flooring repairs caused by damp Improve rainwater disposal system	£5,000
186	28 June 2017	Botus Fleming, St Mary's	Replace lead valley and renail/replace both inner valley roof pitches	£6,500
185	28 June 2017	Charlestown, St Paul's Church,	Works to the south façade of the Church: replacement of the roof slates to the Nave, South Transept and Chancel and associated leadwork; replacement of rusted iron ferramenta and security grilles to the clerestory windows, aisle windows and transept windo	£4,000
184	28 June 2017	Grampound, St Nuns	Removal of the inside plaster of the building due to inappropriate materials being used The Belcote requires pointing in order to stop water migrating into the West wall of the building Part of the present flooring requires taking up due to rot, and the	£2,000

183	28 June 2017	St Just Free Church	To main Church building: Remove all existing life-expired slates and replace with new wet-laid; Repair or replace rotten or damaged roof-level timbers, including guttering supports, bargeboards etc. as needful Remove all existing rainwater goods and repla	£2,000
182	28 June 2017	Liskeard, St. Martin's	The gas fired blown hot air heating system has failed totally and cannot be repaired. We have been advised that the most suitable replacement that is permissible, for a church of this size, is underfloor heating. This will involve substantial reordering	£3,650
181	28 June 2017	Par	To undertake major masonry repairs, internal timber repairs and improvements of floors and other elements to the crumbling spire and tower; conserving the tower and spire for future generations.	£4,300
180	28 June 2017	Stratton Methodist Church	The gas boiler is 13 years old and leaks; it has failed to operate on several occasions this last winter. The radiators do not extend into the organ area nor the area beyond the Communion Rail, including the pulpit. The boiler is inconveniently housed u	£1,250
179	22 March 2017	St Uny	The architect has identified serious problems with the floor, part of which is already unusable. So far, we have raised £ 90,000 of the £ 141,000 (plus VAT) needed. Our latest quinquennial inspection took place in September 2016 and confirms the urgency o	£500
178	22 March 2017	Cawsand Congregational Church	Guttering and downpipe replacement needed on one side of the church. Also treatment for woodworm damage, not yet serious, but preventative measures needed, especially in roof timbers. This is a re-application after further work has been revealed by a QI.	£3,500
177	22 March 2017	St Winwaloe Church, Tremaine	Repairs required on the church were identified in a Quinquennial Church Inspection Report prepared on the 18th June 2014, including: filling open joints in stonework on the church tower and walls; repairing pointing to tower pinnacles; repairing split lea	£6,000
176	22 March 2017	St John the Evangelist, Treslothan	Roof repair and maintenance works as recommended within the most recent quinquennial survey report. Works will involve the stripping and re-slating of the Chancel and Lady Chapel roofs, which are heavily dilapidated, along with maintenance repairs to slip	£3,000
175	22 March 2017	Lanner, Christ Church	Replace Roof	£8,000
174	22 March 2017	Jacobstow, St James	Restore two altar oil paintings	£1,000
173	13 October 2016	St Veep Parish Church	Tower and Bells	£10,000
172	13 October 2016	Sancreed, St Creden	Roof	£12,500
171	13 October 2016	Quethiock, St Hugh	Internal Roof Slats	£3,000
170	13 October 2016	Mullion, St Mellanus	Plaster	£2,000
169	13 October 2016	Lanteglos-by-Camelford, St. Julitta.	Roof	£12,000
168	13 October 2016	Laneast	Medieval Windows	£14,500
167	13 October 2016	Gunwen Methodist Church	Roof	£5,000
166	13 October 2016	Devoran St John and St Petroc	Tower and Gables	£3,500
165	22 June 2016	St Winnow Parish Church	Tower	£5,000
164	22 June 2016	Temple	Roof	£15,000
163	22 June 2016	Parish Church of St. Dominica & St. Dominic, St. Dominick	Plaster and Tiling	£2,000
162	23 March 2016	Truro Cathedral	Major Roof Works	£5,000
161	23 March 2016	Perranporth Methodist Church	Clean and Overhaul Chapel Organ	£500
160	23 March 2016	Penryn Methodist Church	Water damage to Gutter Boxes, Flooring and inside stairwells.	£1,200

159	23 March 2016	Penryn Highway Community Church Centre	Windows and Lighting	£1,000
158	23 March 2016	St. Mawgan in Meneage	Extensive roof and other works.	£5,000
157	23 March 2016	St Gorran Church	Tower	£2,500
156	23 March 2016	Guval Parish Church	Roof	£3,200
155	23 March 2016	St Cubert	Roof and rainwater goods	£5,000
154	23 March 2016	Cawsand Congregational Church	Rainwater goods and woodworm	£2,500
153	07 October 2015	Zennor	1. Remove the pews from the side-chapel and store 2. Remove the t&g timber platform around the altar and store. 3. Dig out and repoint internal walls with a lime sand mortar 4. Repair the wood block floor and treat with preservative. 5. Reposition the	£5,400
152	07 October 2015	Redruth, St Euny	The repair work to be carried out is to the lychgate which has unfortunately fallen into disrepair because it has previously been cement rendered, It needs to be lime rendered in the traditional manner.	£3,275
151	07 October 2015	Quethiock, St Hugh's	The report from our surveyor highlights that the nails holding the roof slates in place have nail sickness and are failing. Since the report we have had over 20 slates slip. The leaking roof risks the coloured wagon roof ceiling as well as damaging the int	£9,700
150	07 October 2015	Paul	Entire memorial window frame will be removed, replicated in Forest of Dean stone and replaced; the glass will all be removed, cleaned, re-leaded and re-fitted into the new framework.	£9,250
149	07 October 2015	Truro, St Clement,	Complete re-roofing -Roof structure repairs -Replacement of lead valleys -Repointing -Overhaul rainwater goods and improve low level drainage -Repairs to ceiling	£3,950
148	07 October 2015	Tintagel	Remove slate slabs from east of screen Remove tiles from the west of screen Carefully remove soil from each side of the sill avoiding as much loss of decayed material as possible. Have archaeologist inspect/examine soil around and under sill Introduc	£8,300
147	07 October 2015	Sennen	Organ Restoration	£2,550
146	22 June 2015	St Goran	We want to open up the 13th century doorway in the north wall of the church and provide a new access to the doorway. This will provide a much needed disabled access to the church and also help to solve the damp problems at the west end of the church. This	£0
145	22 June 2015	Pillaton and St Mellion	This is a request for a follow-on grant for re-pointing the outside walls of both churches to replace failed inappropriate cement based pointing. This is to augment the work being carried out inside the church at Pillaton.	£2,000
144	22 June 2015	Lelant, St Uny	Floor has to be replaced and at the same time it was decided that we would take the opportunity of place the heating system under the new floor in the interest of efficiency.	£4,500

143	22 June 2015	Altarnun, St Nonna	Replacement of existing (failing) organ with better second-hand instrument. Replacement organ already purchased and stored (disassembled) in St.Nonna's.	£5,000
142	22 June 2015	St Neot	The church Tower is leaking and damaging the interior including the frames of two windows. We need to replace some masonry and completely repoint the Tower. The church has been placed on the English Heritage 'At Risk' Register.	£5,000
141	22 June 2015	St Ewe	Repair and replace missing roof slates: Provide replacement lead flashing to main roof valley Rake out cracks in vestry chimney stack and replace in lime mortar	£3,000
140	22 June 2015	Boconnoc Church	Re-lead parapet to south; Re-lead north parapet/valley; Patch repair or re-lead central valley Re-slate where lead attended to Point open joints and lead to coping stones Re-set and point southern parapet stones on lead Renovate other aspects of guttering	£3,000
139	20 March 2015	St.Piran & St. Michael, Perranuthnoe	Details about the repair work: Remediation of damp issues to Church walls; 1) Remove internal plaster and replace with bag rub lime pointing. 2) Rake out and repoint external walk with lime momr. 3) Improve external surface water drainage. 4) Overhaul rai	£9,100
138	20 March 2015	St Stephens-by-Saltash	The tower has suffered ingress of water going back to 1934. With the heavy rain and wind of last winter the repair has become more urgent before further damage takes place. A complete rope survey of the tower by an architect and builder has been completed	£3,000
137	20 March 2015	St John the Baptist and St John-in Cornwall, Torpoint	To replace the ceiling in the Nave and Chancel. To remove and replace the tiles and underlying screed in the Chancel	£6,500
136	08 October 2014	St Just Free Church	To main Church building: Remove all existing life-expired slates and replace with new wet-laid; Repair or replace rotten or damaged roof-level timbers, including guttering supports, bargeboards etc. as needful Remove all existing rainwater goods and repla	£3,000
135	08 October 2014	Polperro Methodist Church	A recent quinquennial advised that important electrical work needed to be done to improve safety. Also signs of active woodworm were detected so a survey was recommended [and has now been made]. Last winter the heating broke down. The present control sy	£2,000
134	08 October 2014	St Keyne	The repairs are necessary following a lightning strike on the church tower, causing one pinnacle to fall damaging the church tower roof and main the church roof in various places, before landing in the nave roof valley as well as destroying the electrical	£3,500
133	08 October 2014	Riverside United Church	2010 quinquennial noted that roof may need replacing soon. Major problems with water ingress over last 12 months. We decided patching/repair would not be cost effective as this would only delay need for new roof. So Phase 1 is to put on a new slate roof.	£7,000
132	08 October 2014	St Mawgan in Meneage	Rewire Church, new distribution board, replace lights Refurbish Porch gate and decorative ironwork Refurbish Front gate arch and lantern Rebuild stub wall by South Gate Repair South Gate	£3,000

131	08 October 2014	Launceston, St Mary Magdalene	The church is a three aisle building with central nave, north & south aisles and chancel comprising Choir & Sanctuary. The aisles are separated by granite columns supporting a slightly pointed wagon roof with carved angels ranged along the wall plate, bar	£4,000
130	30 May 2014	St. Stephen – in - Brannel	Roof slating & Lead & Dry Rot repairs	£5,000
129	30 May 2014	Pillaton Church	The church was hit by lightning in January 2013 resulting in over £300,000 repair bill. The church reopened for Remembrance Day service with the church full and the bells ringing again. This was mainly covered by EIG insurance but £16,000 of non-insurance	£2,500
128	30 May 2014	Penzance Catholic Church	Replace rotten basement windows	£1,850
127	30 May 2014	St Hugh's, Quethiock	The lead in the gully between the North aisle roof and the Nave roof has failed . The rain leaks in and is collected in buckets. We are going to replace the lead, woodwork and failed slates. The sounding Chamber floor is rotting,(leaks from the tower ro	£4,600
126	30 May 2014	Paul Church	<ul style="list-style-type: none"> • Wooden frame of Georgian glass window at the east end of the church is badly rotted in places and in need of repair. • A large piece of stone has fallen from the window surround in the tower and other areas of stone in the vicinity are unstable. • Two s 	£3,500
125	30 May 2014	Stoke Climsland Parish Church	To remove all cementitious pointing and repoint with a lime mortar of an appropriate strength and colour. Where necessary, grind out slate joints to sufficient depth to allow sound repointing in lime mortar. South Elevation - Belfry Stage and Parapet Sout	£3,200
124	30 May 2014	St Tudy	Removal of pews at the rear of the Church and replace cleared area with Delabole slate: Lay under-floor heating units beneath the cleared area of the rear of the Church. Fitting of under-seat heating throughout the rest of the Church including Chancel Pew	£3,000
123	08 March 2014	St Nicholas Church, Tresco	Restore the roof, external repointing and replastering of the south elevation together with internal repairs.	£3,500
122	08 March 2014	St Joseph's Catholic Church, Hayle	Scaffold, rainwater goods, windows and exterior painting.	£2,500
121	08 March 2014	Gwennap	Re-roof the exterior north and south slopes of the church, and the gables over the porches	£5,000
120	08 March 2014	St. Dominic	The existing slate coverings on the Church roof are showing considerable distress, particularly on the north slope of the north aisle. A recent professional inspection of the north aisle roof indicated that slates are continuing to become loose or have mo	£3,000
119	08 March 2014	Veryan, St Symphorian	Replacement of 100yr old pumped radiator system that is beyond economic repair with a network of under pew heaters in order to provide localised warmth and four fan assisted storage heaters to provide background warmth and to sustain the fabric of the Chu	£4,000
118	08 March 2014	Ladock	Replastering of the south internal wall and decorating the church with lime wash (eligible part of larger ineligible kitchenette scheme)	£3,500
117	09 October 2013	Cury, St Corentyn	Raking out and re-pointing with lime mortar all faces of the Tower	£3,000
116	09 October 2013	Mevagissey, St Peter's	Painting and decorating interior of church. Scraping away loose and peeling paintwork. Treating all areas showing signs of mould and mildew with de-fungicide. Filling, sanding and smoothing where necessary. Applying two coats of emulsion throughout. This	£2,000
115	09 October 2013	St Austell Friends Meeting House	The project is to complete urgent high level repair and maintenance work as identified by the Quinquennial inspection in 2012. This highlighted repairs to roof slates, the ridge and hips, replacement of the fascia to all elevations, repairs to wallplates,	£2,500

114	09 October 2013	Newquay Christian Centre	The heating system was presumably installed in the church when constructed (it is a wet system) with old narrow bore boiler pipe giving the radiation and a few radiators hung in various places. The system is not only antiquated, but it is also non enviorm	£2,000
113	09 October 2013	Truro, St. George the Martyr	1. Repairs to tower floor & improve access 2. Repairs to both transept gables – slipped coping stones 3. Overhaul of rainwater goods at high and low levels	£3,000
112	28 May 2013	The Sacred Heart and St Ia, St Ives	To remove 12 diamond pattern windows To completely restore all windows using existing glass and replacing broken panes with glass to match as near as possible. To remove existing hoppers and replace windows as required To re-fix all panels to openings an	£2,500
111	28 May 2013	St Austell Baptist Church	Over the years a number of roof slates have had to be replaced as the nails securing slates have corroded and failed, causing some slates to fall. Replacing the entire roof has now become, not only a matter of safety but also one of econom~cn ecessity as	£3,500
110	28 May 2013	Innis Chapel	Chapel roof and porch in urgent need of a complete re-slate to modern standards.	£3,000
109	28 May 2013	The Collegiate Church of St Endellion	Extensive urgent repair work is required to the roof The South slope of the North Aisle requires re-slating The North slope of the Nave Roof must be re-slatted The North Valley Gutter needs renewing and widening Defective haunching and pointing to gable pa	£5,000
108	28 May 2013	Lezant Church	Repair of roof slopes and reslating as necessary with rag slates. Repair of two valley gutters and overhaul of rainwater goods.	£4,500
107	20 March 2013	St Piran & St Michael's Church, Perranuthnoe	Restoration of East Window, modification of lighting in the nave, upgrading of electrical works to meet modern standards, further restoration of the West Door , and renewal of storage space in the Tower area for vestments and Church effects. In addition w	£3,000
106	20 March 2013	St Michael Caerhays	Repair and restore two Willimott windows (north transept and south aisle), repair stonework as necessary. The work on the stained glass will be carried out by Susan Ashworth (stained glass artist and conservator).	£4,000
105	09 October 2012	Camelford Methodist Church	Re-roofing (and installation of disabled toilet & fire escape which is not the subject of a grant application but included in the project cost)	£2,500
104	09 October 2012	St Mawgan-in-Meneage	The central heating boiler is irreparable. The boiler room roof is collapsing and will need to be replaced before a new boiler is installed. We are also advised that the old pipe work should be taken out and replaced with radiators. Due to the urgency	£3,500
103	09 October 2012	St Michael Caerhays	Repair and restore 2 Willimott windows (north transept and south aisle), repair stonework as necessary. The work on the stained glass will be carried out by Susan Ashworth (stained glass artist and conservator).	£5,000
102	09 October 2012	Truro, St John	Restoration of the 'Resurrection' apse mural	£2,000
101	09 October 2012	Probus, St Probus and St Grace	Window 3: To replace missing stained glass pieces, re-lead and removal of existing ferrous ferramenta with brass bar. Deal with Cills and traps. Repair /replace damaged stonework. Window 4: Add new exterior grill, re-lead window as necessary and remov	£2,000

100	09 October 2012	Flushing, St Peter's	Rainwater goods, rendering. Repair to external wall rendering, particularly coloured mortar to mouldings round window openings and gable parapet mouldings	£2,082
99	09 October 2012	Gunwalloe, St Winwalloe	Phase One Hack off all interior plaster Consolidate walls as necessary Mortar and bed rake out joints Phase Two Bag rub plaster after walls have settled Lime wash interior walls NCT (through CHCT) Gave £2,500 for Phase One, This application for Phase two	£3,500
98	09 October 2012	Ruanlanihome, St Rumon's,	The Quinquennial report of 2008 noted that major conservation work to the church windows was needed. In May 2011 a report was commissioned from Alan Endacott of Angel Stained Glass, Lewannick. The report noted that nine of the twelve windows required re-l	£3,000
97	12 June 2012	St. Keverne Parish Church	The existing wiring is aged and worn and must be replaced and it for this we would appreciate your help. The development plan and faculty permission includes a complete re-wire of the entire building, as appropriate, to support the proposed lighting, soun	£2,500
96	12 June 2012	St Buryan	St Buryan were awarded a grant of £6k (£3k CHCT + £3K Manifold) in Oct 2011. They have asked us to reconsider the grant in the light of an increase in costs from £261K to £359K with no increase in the EH grant. Details in the letter dated in the grants	£4,000
95	12 June 2012	Duloe, St Cuby	Conserve the tombs and slate memorials in the Colshull chapel.	£4,000
94	12 June 2012	St Enoder	The project is to complete urgent high level repair and maintenance work as identified by the Quinquennial inspection in 2010, which highlighted the work as being top priority. The work will include re-roofing all but a small portion of the church	£5,000
93	12 June 2012	Dobwalls United Church	The external stone walls of the Chapel building, which at the moment are painted grey and causing a problem with damp, will be stripped back to the stone work and treated, therefore making the exterior of the whole of the building the same. We will then	£2,500
92	24 March 2012	Wadebridge Christian Centre	Repairs to the roof which is constructed of Delabole rag slates, which are worn and thin. The roof needs a full overhaul - felting, battening and replacing of worn roof slates, with new fasclas and guttering.	£1,000
91	23 March 2012	Tresmere, St Nicholas	Floor and Pew Repairs Rainwater Goods Window Repairs	£4,000
90	22 March 2012	Manaccan CHCT Grant includes £3,000 from Manifold Trust	Roof Repairs. Fix sacrificial lead on both sides of gully. Replace plastic guttering with cast iron plus down pipes Prime undercoat and gloss. Clean out tower debris, clean moss etc. from roof and repair broken and damaged slates. Belfry Door. (at pre	£6,000
89	21 March 2012	Mevagissey, St Peter's	Rainwater goods. Cleaning, Painting, replace brackets	£950
88	12 October 2011	St John the Baptist, Pendeen	Hack off all interior plaster Consolidate walls as necessary Mortar and bed rake out joints	£2,500
87	12 October 2011	St Buryan CHCT Grant includes £3,000 from Manifold Trust	The work is essentially high level repairs to the roof and valley guttering. Both valleys over the arcades need re-leading; all six slopes of the roof require re-slating; guttering and downpipes need refurbishing; several rotten roof timbers need replacin	£6,000

86	12 October 2011	Davidstow, St David	Major repairs to tower masonry, roof, floors and belfry. Also replace bell frame.	£5,000
85	12 October 2011	St Levan	1. Under drawing of ceilings with Glasroc boarding to internal plaster 2. Internal plaster patching, lime washing and internal decorations 3. Work to the main roof, where there is ingress of water against the tower.	£2,500
84	12 October 2011	St Just In Roseland	Complete roof restoration. Overhaul and repainting all rainwater goods. Cut out defective pointing of the upper tower masonry and renewal with lime mortar. Repairs to the north belfry opening following detailed inspection. All the above work to be carried	£5,000
83	12 October 2011	Boconnoc Church	Re-slate Roof	£2,500
82	12 October 2011	St Winwalloe, Gunwalloe	Hack off all interior plaster Consolidate walls as necessary Mortar and bed rake out joints	£2,500
81	13 June 2011	Tuckingmill, All Saints	This church dates back to 1845 and was built by the Bassett family. Existing external Stone-work is of red sandstone, with granite window and door surrounds, string courses, plinth and pilasters. Over the years the sandstone has eroded and water penetrati	£2,500
80	13 June 2011	Maryfield Church, Torpoint	There is a need to repoint all faces of the spire using a lime based mortar. At the apex of the spire there is a slate cap supported by iron bars which are corroded to such an extent that the slate cap is unsafe and needs replacing. One bell louvre is mis	£2,000
79	30 March 2011	Cury, St Corentyn	Re-Wire and re-visit of application of 10 03 25 for Replacement of bell support framework. Total removal of the bell installation Including bells and all other components. Severe corrosion of main and secondary RSJ's.	£2,500
78	30 March 2011	St Stythians, Stithians	Roof and Tower. Subject of English Heritage Grant	£4,000
77	30 March 2011	St Issey	Two reinforced concrete ring beams were installed during the 1950's to strengthen the tower's stonework. Major corrosion has taken place since, making it dangerous to ring the six bells, and threatening the security of the tower. 1950's repairs must be re	£2,500
76	30 March 2011	Landulph, St Leonard & St Dilpe	The important 17th Century carved wooden panelling, which used to be pew ends and were put on the back wall when the pews were renewed at the beginning of the 20th century, need repairing as they have become very damp and (some are rotting) against the wa	£2,000
75	30 March 2011	Beacon Methodist Church	Deterioration of the stonework mainly due to frost damage	£2,500
74	30 March 2011	St Dominic	(a) Replacement of heating boiler, replacement and extension of the heating system; (b) Erection of a glass Tower Screen; and (c) Creation of a Family Area.	£2,000
73	30 March 2011	Jacobstow, St James's	Roof: Valley and Tower	£4,000
72	30 March 2011	Penzance, St Mary's	One of the beams which supports the gallery on the S.W. side of the church has started to rot where it is exposed to the full force of the prevailing and very wet, southwest wind. The church surveyor has decided that the end of this beam and the other two	£2,500
71	30 March 2011	St Paternus Church, North Petherwin	Weld/repair bell no. 2 which is cracked, thus disabling the quarter chimes of the clock. Repair & refurbishment of the fixtures & fittings of all the six bells in the ring. These have come to the end of their useful life, and they will soon become unsafe	£1,000

70	30 March 2011	Bodmin, St Petroc	Complete new lighting scheme new sound system: moving of Font to a more theological position together with cleaning to also give it space and dignity.	£2,500
69	14 October 2010	St Morvetha, Morvah Includes £5,000 from the Manifold Trust	The lead to the tower roof needs to be replaced. Remedial works to the nave walls which have displaced possibly due to roof structure movement. Slate roof to the north side needs replacing. Currently there is water penetration to the tower and roof which	£6,000
68	14 October 2010	St Juliot, Boscastle	Tower Weather proofing Replace cracked Quoins	£2,000
67	14 October 2010	Helston, St Michael	Re-roof	£5,000
66	14 October 2010	Lizard Methodist Church	Enhancements to the heating system	£250
65	14 October 2010	St Illogan Church Includes £5,000 from the Manifold Trust	Re-roof	£10,000
64	14 October 2010	Roche, St Gomonda	Roof	£3,500
63	14 October 2010	Penwerris Includes £5,000 from the Manifold Trust	Re-roof	£10,000
62	14 October 2010	Boconnoc Church	Work to replace a heating system and to improve Boconnoc's suitability as a community resource	£1,000
61	14 June 2010	St. Clether – The Parish Church of St. Clederus	To overhaul, restore and install a 2 Manual Hele Pipe Organ at the west end of north side. To remove three pews at the west end on north side. To run an electric cable extension from the electric socket on north wall of tower to new socket on north wall	£2,500
60	14 June 2010	Towednack Parish Church	Tower Roof: Lead Repairs	£500
59	14 June 2010	St Michael Caerhays	Restoration of first two of ten stained glass windows made and installed by Revd William Willimott [phase one of several]	£3,500
58	14 June 2010	Cubert, St Cubert	New North Door Repair to interior of Tower, Bell Frames and Bells Repair to War Memorial Repair to ceiling of S Transcept	£4,000
57	14 June 2010	Carn Brea Village Methodist Church	Repointing and associated barge board repairs	£2,000
56	25 March 2010	Cury, St Corentyn	Replacement of bell support framework. Total removal of the bell installation Including bells and all other components. Severe corrosion of main and secondary RSJ's.	£2,000
55	25 March 2010	Washaway, St. Conan's	Complete Reroofing	£2,000
54	25 March 2010	Rame, St Germanus	Nail sickness; Re-Roof EH Declined a grant - not urgent	£3,500
53	25 March 2010	Perranuthnoe, St Michael and St Pirran	The clock mechanism is supported on 2 RSJ beams. A recent survey highlighted corrosion in the wall and the recommendation by the Cumbria Clock Co Ltd that they be replaced. Further advise from an independent Structural Engineer suggested from a safety sta	£1,000

52	25 March 2010	Altarnun, St Nonna	Restoration of Bells and Bell-frame: Bells – quarter turn, new bearings Frame – two new framesides, galvanise whole frame, new supporting grillage. Fittings – new pulleys, stays, sliders, and running boards.	£2,000
51	25 March 2010	Redruth, St Andrew's	(a) replacement of central heating boiler and radiators in church (see business plan) (b) repointing of West Elevation of church which is currently letting in water	£3,000
50	25 March 2010	Newquay Christian Centre	The roof of the building has suffered nail rot for many years and has been getting progressively worse as the years have gone by. It is now at a stage where re-roofing is absolutely necessary, along with new lead work and guttering. Water ingress is stave	£2,500
49	25 March 2010	Shevioc, St Mary's	Repairs are required to the: South Transept The Main Church Body and extrmally	£2,500
48	25 March 2010	St Mellion, St Merlanus	Refurbishment of rainwater goods Re-pointing of Stonework Internal plastering	£4,000
47	25 March 2010	Morwenstow	Replacement of structurally critical main beam supporting tower roof, the existing beam having been severely weakened by rust and being beyond repair.	£2,000
46	13 October 2009	Truro Cathedral	Deterioration of the limestone components, which form the major part of the Victoria tower	£5,000
45	13 October 2009	Tregony Congregational Church Fore Street Tregony	Part replacement windows Heating System - replace electric convection with radiators run through from next door hall	£2,500
44	13 October 2009	St Martins and St Meriadoc Parish Church, Camborne	Replace tiled aisles, flooring, heating system, electrics and joinery	£5,000
43	13 October 2009	St Briochus, Lezant	Assorted work to Tower, Lead, Rainwater goods and pointing	£3,000
42	13 October 2009	Our Lady Of The Portal And St. Piran, Truro	Deteriorating lead work over the altar causing damage and disruption required immediate attention. New lead and associated wood and roof replacement needed.	£1,500
41	13 October 2009	St John's Church Truro	Roof and High level Repair	£2,500
40	13 October 2009	Parish Church of SS Probus and Grace, Probus	To repair and renovate stonework and stained/ plain glass in most of the church windows, including broken pieces (in stained glass windows) and panes (in plain glass windows.) The project is also to replaced corroding iron window ties with non-ferrous typ	£3,000
39	22 May 2009	Troon Methodist Church	Repair defective plaster and re-point	£2,500
38	22 May 2009	St Cuby's Duloe Includes £5,000 from the Manifold Trust	Restore roof and rainwater goods	£10,000
37	22 May 2009	Mullion Methodist Church	Clean, and repair three stained glass windows	£1,500
36	22 May 2009	St Pol-de-Leon, Paul, Penzance	Window restoration project	£4,000
35	22 May 2009	St Newlyna, St Newlyn East	Lead, timber and rainwater goods repairs	£5,000
34	22 May 2009	Fowey Parish Church	Restore main roof	£4,000
33	22 May 2009	Come to Good Meeting House Includes £5,000 from the Manifold Trust	The project concentrates on high level roofing repair and maintenance to the exterior fabric	£9,000
32	26 March 2009	St Endellion	Replacement of Lighting System	£1,000
31	16 October 2008	Zion Congregational Church, St Ives	Replacement of Church Hall Roof (used for occasional worship)	£2,800

30	16 October 2008	Gulval	Repair of bulges in retaining wall enclosing island containing church and graveyard	£1,500
29	16 October 2008	St John's Treslothan	Removal of dangerous masonry (Church is £8,000 in debt). Geoffrey will brief at the meeting	£350
28	16 October 2008	St Symphorian Veryan	Work on Windows (Joanna is visiting and will report to meeting)	£4,000
27	16 October 2008	St Sampson Golant Includes £1,000 from the Manifold Trust	Removal of cement pointing and replacement with lime mortar. Replace wall plates to bell chamber; replace floor in deadening chamber. Unseal window in chamber and replace with louvres.	£5,000
26	25 May 2008	St Winnow Includes £4,000 from the Manifold Trust	Restoration of important stained glass window. Includes £4,000 extra-ordinary grant	£8,000
25	25 May 2008	St Stythians, Stithians	Re-slate north slope, repair southern lead valley	£4,000
24	25 May 2008	Lanner Methodist Church	New Roof Needed	£2,500
23	25 May 2008	St Blaise	Heating system: required to maintain good condition of recently restored roof	£1,000
22	25 May 2008	St Paternus, North Petherwin	Tower and parapet work	£2,500
21	06 March 2008	St Piran & St Michael's Church, Perranuthnoe.	Tower Restoration	£3,500
20	06 March 2008	St Eval	Rebuilding of Pinacles	£4,000
19	06 March 2008	Lostwithiel St Bartholomew	Work on Spire (Grant additional to £4,500 made in Sep 07)	£4,500
18	17 October 2007	St Mabyn	Restoration of church roof	£5,000
17	17 October 2007	St Austell, Holy Trinity	Replacement of lead gullies in north and south elevation. Lead flashing around tower and elsewhere.	£4,500
16	17 October 2007	Pillaton St Odulph	Window Stained glass repairs	£500
15	17 October 2007	St Dominick	Repairs to rainwater-goods	£500
14	17 October 2007	Penzance Chapel Street Methodist	Heating system repairs	£3,000
13	17 October 2007	St Mellion	Window Stained glass repairs	£500
12	17 October 2007	St Clement Withiel	Move of Wedlake organ to reveal Tudor east window with a small amount of Tudor stained glass (Crest of Prior Thomas Vyvyan)	£3,000
11	17 October 2007	Phillack St Felicitas and St Pail	Re-slatting and leadwork. Complete rainwater-goods upgrade.	£4,000
10	17 October 2007	Lostwithiel St Bartholomew	Re-pointing spire	£4,500
9	15 May 2007	Newquay Reformed Baptist Church	Re-plaster the internal ceiling of our main church area.	£1,000
8	15 May 2007	Mullion Methodist Church:	Replacement of all downstairs windows	£400
7	15 May 2007	Redruth Methodist Church:	Organ repairs	£750
6	15 May 2007	St Mary's Roman Catholic Church Falmouth	Repair upper area of Bell Tower and install second finial for lightning protection.	£1,000
5	08 March 2007	St Stythians, Stithians	Renovation of Floor of raised west-end of Church, replacement of rotten joists and boards.	£3,000
4	08 March 2007	Gwithian Methodist:	Re-thatching following Thatch collapse. Walling repairs, lime-washing, some joinery work.	£2,800
3	08 March 2007	Falmouth, All Saints	Total renovation of East Window and surrounding stonework. Provide security screen	£4,000
2	08 March 2007	Friends Meeting House, Marazion	Disabled access and general repairs	£2,000
1	08 March 2007	Constantine Church	Tower and Pinnacles. Replace rusting RSJs with Oak Beams, re-pointing	£3,500
				£1,089,345